PAPER • OPEN ACCESS

Stabilizer for reversing vertical spindles in the drum removal area of cotton-picking apparatus

M Shoumarova¹, T Abdillayev¹ and Sh A Yusupov¹

Published under licence by IOP Publishing Ltd

IOP Conference Series: Earth and Environmental Science, Volume 1231, International Conference on Agricultural

Engineering and Green Infrastructure Solutions 28/03/2023 - 30/03/2023 Tashkent, Uzbekistan

Citation M Shoumarova *et al* 2023 *IOP Conf. Ser.: Earth Environ. Sci.* **1231** 012006 **DOI** 10.1088/1755-1315/1231/1/012006

sher_xxx89@mail.ru

¹ Tashkent Institute of Irrigation and Agricultural Mechanization Engineers (National Research University), Tashkent, Uzbekistan

Buy this article in print

Journal RSS

Sign up for new issue notifications

Create citation alert

Abstract

The main indicator of the quality of the cotton harvesting machine is the completeness of collectingPDF

the grown crop into the bin, which is usually 3-4% lower than the completeness of collecting Help spindles. This is because the remover of vertical-spindle machines does not fully remove the cotton bobbins from the spindles. Part of the cotton wound on the spindle is carried away into the working zone without being removed. This phenomenon is called "cotton carry-over". According to previous authors, "Carry-over" reaches 3-4% of the spindle collection completeness. This happens because the spindle roller, after leaving contact with the external belts, rotates by inertia and when it see our Privacy and Cookies policy.



encounters the inner belts of the removal zone, the spindle suddenly slows down to change the direction of rotation. Here, due to the braking, the cotton bobbin falls off the spindle by "selfrelease". If the braking is excessive, some cotton bobbins lose their grip on the spindle and remain

This site uses cookies. By continuing to use this site you agree to our use of cookies. on it as a free ring. If the brush remover does not remove this "ring", it is "carried over" by the To find out more, spindle into the working zone. This process reduces the completeness of the collection in the hopper. In order to ensure the stability of cotton collection by the spindle, it is necessary to provide an increased pulling force of the friction drive in the working zone. In our experiments, this was achieved by replacing the conventional V- belts of the drive with multi-ribbed belts. Multi-ribbed belts increase the pulling force by 1.5 times because their grip with the small radius roller is improved. In the removal zone of the drum, it is also necessary to install multi-ribbed belts, which, due to their better grip, brake the spindle more sharply and increase carry-over. To reduce this process, a stabilizer is installed on the head of the reverse rotation brake, which allows the braking process to be adjusted. This article provides materials explaining the design of this stabilizer. Export

citation and abstract BibTeX RIS

Previous article in issue

Next article in issue



Content from this work may be used under the terms of the Creative Commons Attribution 3.0 licence. Any further distribution of this work must maintain attribution to the author(s) and the title of the work, journal citation

and DOI.



You may also like

Help

PDF



An AFM-based methodology for measuring axial and radial error motions of spindles

Spectral and temporal characterization of sleep spindles-methodological implications

Parameters of the stabilizer of the poly-V belts of the drive of vertical spindles for stable cotton harvesting performance

Effect of the design parameters of the spindle knot on natural frequencies

Resonance speed measurement of high-speed spindle using an instruction-domain-based approach

Quality of friction drive moving spindels of cotton picking machine with vertical spindel This site uses cookies. By continuing to use this site you agree to our use of cookies. To find out more,

PDF

Help

This site uses cookies. By continuing to use this site you agree to our use of cookies. To find out more,

